RETURN TO TECHNICAL SERVICE BULLETIN TABLE OF CONTENTS
RETURN TO CD-ROM TABLE OF CONTENTS

TECHNICAL SERVICE BULLETIN #1

Product: Fabius Tiro

Date: November 18, 2003

Re: Inlet Shield Installation

Reference Doc: Product Bulletin #154, Service Procedure - SP00285

Reason/Rational: Enhancement

Solution/Procedure: Install Inlet Shield on all Fabius Tiro units shipped from DMI per above Service Procedure and complete Return Form (attached) and return to DMI/DS within 7 days of completion.

Devices affected: S/N 10004 – 10008, 10013 - 10016, 10018 – 10034, 10036 - 10038, 10044 – 10046, 10060 - 10072

Timing/When: Before device installation or at next service visit. But, no later than 30 days from date of this TSB.

Additional Info: Perform SP00285 – Inlet Fitting Shield Installation

Cost: Inlet Shield Kits come at no charge to the customer and are installed under warranty.

Ordering Info: Contact your DMI Customer Service Representative to order the Inlet Shield Kit using part number 4118541.

Distribution: DrägerService & All Authorized Service Organizations worldwide, except North America.

DrägerService
3122 Commerce Drive
Telford, PA 18969
Tel: (215) 721-5402
(800) 543-5047
Fax: (215) 723-5935
Web: www.draegermedical.com
DrägerService is a division of
Draeger Medical, Inc.

RETURN TO TECHNICAL SERVICE BULLETIN TABLE OF CONTENTS
RETURN TO CD-ROM TABLE OF CONTENTS

Return Form – Inlet Shield Installation

Distributor/ASO:	Customer:
Country:	Address:
	City:

Machine S/N	Machine S/N	Machine S/N
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Fax To:
DrägerService
Attn: Al Myers
(215) 721-5784

Date of Update _____
Signature (TSR) _____
Name (Print) _____

DrägerService
3122 Commerce Drive
Telford, PA 18969
Tel: (215) 721-5402
(800) 543-5047
Fax: (215) 723-5935
Web: www.draegermedical.com
DrägerService is a division of
Draeger Medical, Inc.